FDV 50



Operating Instructions

Carriage



Table of contents

General	
Principle	
Device concept	
Scope of supply	
Field of application	
Proper use Warning notices on the carriage	
warning notices on the camage	4
Carriage components	5
Standard equipment	
Options and accessories	5
Controls and connections	6
FCU-9 control unit	
FRC-9 remote control	
FNC-9 Telliote control	
Welding positions	8
Possible welding positions	8
Drawaying the carriers	0
Preparing the carriage	
Checking the surface of the workpiece and the carriage to ensure they are clean	
Carriage strain relief	
Commissioning	9
Checking the connections	9
Switching on system components	9
Defining parameters for the carriage	9
Carrying out test run	10
Starting the welding process	10
Tanaklaskaskin n	44
Troubleshooting	
General	
Basic requirements for the system to work	
Carriage Control, remote control	
Control, remote control	II
Maintenance and care	13
Personnel	13
Maintenance record	13
Maintenance operations and intervals	13
Recommended lubricants	13
Carriage components	14
Technical data	15
Technical data	
FDV 50 carriageFDV 50 dimensions	
FDV 30 differsions	13
Options and accessories	16
System overview	16
Installation kit	16
Connecting cable	16
AAP 22 P	
Wiring diagram	
with one Powersource	
with two Powersources	23
EU-Declaration of conformity	25
,	_

General

Principle

The FDV 50 carriage is a straight-line carriage with a 2-wheel drive for welding mechanised butt and fillet welds in a horizontal welding position.

Device concept



FDV 50 carriage

The FDV 50 carriage has been designed for flexibility and to improve productivity in the execution of longitudinal weld seams.

Robust yet lightweight design allows quick and easy positioning on the workpiece.

The carriage is powered by a mains cable. It is controlled and operated by a remote control.

Scope of supply

FDV 50 carriage 8,045,099 FCU9 / M1 control unit 8,040,026 FRC9 remote control 8,046,016

Field of application

The FDV 50 carriage can be used in all situations where a high degree of flexibility is required when executing longitudinal weld seams:

- Welding of longitudinal members
- Shipyards
- Bridge construction
- Workshops
- Production halls
- Building sites

Proper use

The FDV 50 carriage must only be used for welding mechanised butt and fillet welds in a horizontal welding position.

Any other use shall be deemed improper and the manufacturer will assume no responsibility for any damages arising.

Can be used in the following welding processes:

- MIG / MAG process

Proper use also includes:


- Carrying out all maintenance work at the appropriate intervals
- Keeping a service book with the most important information (date, operator, activities carried out)
- Using the spare parts stipulated by Fronius
- Following all the information in the operating instructions
- Using this document in combination with the operating instructions for the integrated system components (power source, wire-feed unit, etc.)



NOTE! Any use of the machine other than for its intended purpose or any unauthorised conversion or modifications, shall be deemed improper use. Any liability or warranty from the manufacturer is hereby invalidated.

Warning notices on the carriage

A number of safety symbols can be seen on the rating plate affixed to the carriage. The safety symbols must not be removed or painted over.



FDV 50 rating plate


Carriage components

Standard equipment

- 2-wheel drive via AC motor (drive can be uncoupled)
- Wheels with steel tread and groove
- Reinforcement with mounting pin for wire-feed unit
- Power supply and motor controller box integrated in the carriage
- Mains cable and plug (5 metres)
- Control line to power source (6.5 metres)

Options and accessories

- FRC-9 remote control and cable (3 metres)
- Holder for remote control
- Mechanical weld tracking system
- Torch holder and adjustment units
- Steel guide rollers with / without groove (laterally adjustable)
- Rail system
- Limit position function I-kit
- VR holder for two wire-feed units




Controls and connections

FCU-9 control unit



WARNING! Operating the equipment incorrectly can cause serious injury and damage. Do not use the functions described here until you have thoroughly read and understood the following documents:

- These operating instructions
- All the operating instructions for the system components, especially the safety rules



FDV 50 connections


Function

- **Remote control connection** (1) to connect manual remote control
- (2) On/Off mains switch to switch the carriage and connected remote control on and off
- Power source control to connect the power source



NOTE! Detailed information about using the FCU-9 control unit, plus information about maintenance and troubleshooting, can be found in the FCU-9 operating instructions that are enclosed with the technical documents for the carriage.

FRC-9 remote control



FRC-9 remote control

No. Function

- (1) Emergency Stop button
 Stops all movements. The arc is broken immediately.
- (2) Start-up delay potentiometer

 To set the time between igniting the arc and starting the carriage.
- (3) "Move manually" button

 For manual fine positioning of the carriage.
- (4) "STOP" button

 To stop the program sequence.

 Combined with the "START" button, used to determine the direction of rotation.

No. Function

(5) Preselect welding direction

To select the welding direction (direction of travel).

(6) START button

To start the welding process.

(7) Welding ON/OFF

Select program sequence with or without welding.

(8) Pneumatic ON/OFF

To control a pneumatic unit (e.g. lowering of torch).

(9) Welding speed potentiometer

To set the welding speed. This can also be changed during the welding process.

(10) Digital display of welding speed

Displays the carriage speed in [cm/min].



NOTE! Detailed information about using the remote control and setting the desired welding parameters, plus information about maintenance and troubleshooting, can be found in the FRC-9 operating instructions.

Welding positions

Possible welding positions

Exceptional track consistency is assured by the wheels with grooves and the 2-wheel drive, which can be uncoupled.

The following welding positions are possible:

- PA position

Preparing the carriage


Checking the surface of the workpiece and the carriage to ensure they are clean Before positioning the carriage, check the following:

- The surface of the workpiece must be clean (no sand, shavings, etc.)
- The tread and grooves of the drive wheels must not be damaged and must be free of shavings, dirt and welding spatter

Carriage strain relief

To attain optimum wirefeed, observe the following when connecting and routing the hosepack:

- Do not allow the hosepack to become kinked
- Always lay the hosepack as straight as possible
- Suspend hosepack if necessary. Use balancer and hosepack holder.



Hosepack handling

Commissioning

Checking the connections



WARNING! Operating the equipment incorrectly can cause serious injury and damage. Do not use the functions described here until you have thoroughly read and understood the following documents:

- These operating instructions
- all the operating instructions for the system components, especially the safety rules

The following activities and work steps apply to the installed system. All connections must be established. Before start-up, check the connections of the following system components:

- Power source
- Cooling circuit
- Gas cylinder
- Wire-feed unit
- Welding torch with hosepack
- Workpiece

Precise information on the assembly and connection of the system components can be found in the relevant system component operating instructions.

Switching on system components

IMPORTANT! There are no fixed rules for the sequence in which the system components are switched on. They can be switched on in any order.

On the following system components turn the main switch to the "ON - 1" position:

- Carriage control unit
- Power source
- Wire-feed unit (if power is not supplied from the power source)

Defining parameters for the carriage

Determine the following settings for the welding process:

- Start-up delay
- Welding direction
- Traversing speed

Carrying out test run

Perform a test run to check that all system components work together correctly. This is done without an arc and thus allows you to check all movements during the process.

- 1. Switch the "Welding ON / OFF" toggle switch to the OFF position.
- 2. Press the START button. The welding test sequence starts.

IMPORTANT! Never leave the machine unattended, particularly when it is moving automatically.

- 3. Carry out a visual check during the process.
- 4. If necessary, make the relevant corrections (welding torch position, direction of travel of carriage, traversing speed, etc.).
- 5. After the test, move the carriage back to its original position.

Starting the welding process

Start the welding process:

- 1. Switch the "Welding ON / OFF" toggle switch to the ON position.
- 2. Press the START button. The welding process starts.

 IMPORTANT! Never leave the machine unattended, particularly when it is moving automatically.

Troubleshooting

General

In the event of faults, note that the functioning of the entire system depends on many additional components (power source, wire-feed unit, etc.) that are also potential sources of problems.

Basic requirements for the system to work

- Connections established between separate system components
- System components are supplied with electricity and the mains voltage is as specified (see rating plate)

Carriage

Carriage is switched on but does not move		
Cause:	Carriage overloaded (e.g. the torch cables pull the carriage up)	
Remedy:	Relieve cable strain (suspend)	
Cause:	Wheels dirty (with oil)	
Remedy:	Clean the wheels	

Play on the torch		
Cause:	Play on the handles	
Remedy:	Tighten handles	
Cause:	Play on the guide rails	
Remedy:	Tighten the pressure screws	

Control, remote control

Nothing happens, main switch does not light up			
Cause:	Main switch is switched off		
Remedy:	Switch the device on		
Cause:	No connection to the mains		
Remedy:	Check the mains lead, mains plug and mains cable		
Cause:	Mains fuse is faulty		
Remedy:	Replace the mains fuse: glass-tube fuse		

No function, main switch lights up			
Cause:	Emergency Stop has been actuated		
Remedy:	Release the Emergency Stop button		
Cause:	No connection to the carriage		
Remedy:	Check the control line		
Cause:	Frequency converter error		
Remedy:	- Switch the device off		
	- Wait 15 seconds		
	- Switch the device on again		

Control, remote control (continued)

Carriage does not move after start-up or when in inching mode		
Cause:	Emergency Stop has been actuated	
Remedy:	Release the Emergency Stop button	
Cause:	Frequency converter error	
Remedy:	- Switch the device off - Wait 15 seconds - Switch the device on again	

Arc ignites, carriage does not move		
Cause:	Value too high for start-up delay	
Remedy:	Change the "Start-up delay time" parameter (start-up delay potentiometer)	

Carriage moves but arc does not ignite			
Cause:	Power source switched off		
Remedy:	Switch on the power source		
Cause:	Welding ON / OFF selector switch set to the OFF position		
Remedy:	Set the selector switch to ON		

Maintenance and care

Personnel



WARNING! Risk of injury and damage from incorrectly performed maintenance.

All maintenance work on the FDV 50 carriage must only be carried out by trained technicians. It is essential to adhere

to the maintenance intervals and maintenance procedures. The manufacturer accepts no liability for any damage caused by inadequate or poorly performed maintenance.

Maintenance record

The operator must put the following organisational measures in place with regard to maintenance:

 keeping a service book with the most important data (date, operator, maintenance activities carried out)

Maintenance operations and intervals



NOTE! Before beginning maintenance work, switch off device and disconnect from mains supply.

Item	Part	Action	Interval
A	Linear guides	Clean, check oil film, elimi- nate play: tighten pressure screws with Allen key	M
B	Thread play	Clean, regrease	М
C	Rack and pinion	Clean, regrease	М
D	Rollers and rails	Clean, check position	M
E	Ventilation openings	Clean	W
F	Terminal contacts	Clean	W
G	Wheels, underbody, guide wheels, guide rails	Clean	D


D Daily
W Weekly
M Monthly
1/2 y Half-yearly
Y Yearly

Recommended lubricants

IMPORTANT! Lubricants with solid lubricant additives (e.g.: MoS2, graphite and PTFE) are not suitable for guiding systems.

Lubricant	DIN	DIN number	Comment
Lubricating	KP 2-K	51502 / 51825	Lithium soap-based
grease			grease
Lubricating oil	CLP32-100	51517 Part 3	ISO VG 32-100
Conductive paste			Item no. 48,0009,0157

Carriage components




Technical data

FDV 50 carriage

Mains voltage/frequency	230 V / 50-60 HZ
Control voltage	24 V DC
Power consumption	180 VA
Max. load	50 kg
Track width	370 mm
Welding position	PA
Horizontal speed (load = 50 N)	0-199 cm/min
Net weight (without remote control and weld tracking)	41 kg

FDV 50 dimensions




Α	792 mm
В	437 mm
С	345 mm
D	592 mm

E	370 mm
F	1069 mm
G	max. 379.5 mm
Н	678 mm

Options and accessories

System overview



Installation kit

Start/Stop second power source I-kit

Item number: 8,100,107


Including 3 m Tuchel connecting cable

Connecting cable


5 m connecting cable to FTP (pneum. torch positioning)

Item number: 38,0100,0081

FDV-50








48,0529,0000 FDV 50 carriage


Designation:	Item number:
Thrust washer	48,0529,0105
Impeller	48,0529,0106
Impeller drive	48,0529,0107
Drive pinion	48,0529,0108
Intermediate cog	48,0529,0109
Limit switch plate	48,0529,0315
Base frame, complete	48,0529,6000
Drive axis, complete	48,0529,7000
Front axis, complete	48,0529,8000
Base housing	38,0003,0090
Cable gland	38,0004,0041
Spur gear motor	48,0006,0071
Stop bolt without locking nut, with button	48,0007,0053
FCU-9M1	8,040,026
Locking ring	42,0407,0257
Bearing	42,0408,0007
Spring	DIN6885_5x5x36
FRC-9 remote control	8,046,016


48-0385-C000 I-kit Limit switch



Designation:	Item number:
Limit switch 90°	38,0002,0166
Cable connection	38,0004,0090

8,040,026 FCU-9M1










Item no.	Name
4,085,144	MP-Print
38,0006,0087	Mains switch
38,0102,0017	Frequency converter
38,0102,0031	PLC
38,0006,0043	Relay 24VDC 1WI
43,0001,1115	Line filter
43,0001,1397	24 VDC mains adapter
43,0004,3206	5 m mains cable
43,0003,0001	Handle cap
43,0003,0002	Plug connector
43,0003,0148	Plug insert
38,0003,0089	Connector housing
43,0003,0235	Plug insert

Wiring diagram

with one Powersource







EU-Declaration of conformity



EU-KONFORMITÄTSERKLÄRUNG 2016 EU-DECLARATION OF CONFORMITY 2016 DÉCLARATION UE DE CONFORMITÉ, 2016

Wels-Thalheim, 2016-04-20

Die Firma Manufacturer

FRONIUS INTERNATIONAL GMBH

Froniusplatz 1, 4600 Wels

erklärt in alleiniger Verantwortung, dass folgendes Produkt: Hereby certifies on its sole responsibility that the following product: se déclare seule responsable du fait que le produit suivant:

FDV 50 Fahrwerk FDV 50 Carriage FDV 50 Chariot de soudage

La compagnie

auf das sich diese Erklärung bezieht, mit folgenden Richtlinien bzw. Normen übereinstimmt: which is explicitly referred to by this Declaration meet the following directives and standard(s): qui est l'objet de la présente déclaration correspondent aux suivantes directives et normes:

Richtlinie 2006/42/EG Maschinenrichtlinie

Richtlinie 2014/35/EU Elektrische Betriebsmittel Niederspannungsrichtlinie

Richtlinie 2011/65/EU RoHS

Europäische Normen inklusive zutreffende Änderungen EN ISO 12100:2010 EN 60204-1:2006 (18.3 -18.7)

Die oben genannte Firma hält Dokumentationen als Nachweis der Erfüllung der Sicherheitsziele und die wesentlichen Schutzanforderungen zur Einsicht bereit.

Dokumentationsverantwortlicher: (technische Dokumentation)

Ing. Josef Feichtinger Günter Fronius Straße 1 A - 4600 Wels-Thalheim Directive 2006/42/EC Machinery Directive Directive 2014/35/EU Electrical Apparatus Low Voltage Directive

Directive 2011/65/EU

RoHS

European Standards including relevant amendments EN ISO 12100:2010 EN 60204-1:2006 (18.3 -18.7)

Documentation evidencing conformity with the requirements of the Directives is kept available for inspection at the above Manufacturer.

person responsible for documents: (technical documents)

Ing. Josef Feichtinger Günter Fronius Straße 1 A - 4600 Wels-Thalheim Directive 2006/42/CE Directive aux machines Directive 2014/35/UE Outillages électriques

Directive de basse tension

Directive 2011/65/UE RoHS

Normes européennes avec amendements correspondants EN ISO 12100:2010 EN 60204-1:2006 (18.3 -18.7)

En tant que preuve de la satisfaction des demandes de sécurité la documentation peut être consultée chez la compagnie susmentionnée.

responsable documentation: (technique documentation)

Ing. Josef Feichtinger Günter Fronius Straße 1 A - 4600 Wels-Thalheim

(€ 2016

ppa. Magang.H.Hackl Member of Board Chief Technology Officer

DE German Deutsch EN English English FR French Française



FRONIUS INTERNATIONAL GMBH TechSupport Automation

Froniusplatz 1, A-4600 Wels, Austria

E-Mail: support.automation@fronius.com www.fronius.com

www.fronius.com/addresses

Under http://www.fronius.com/addresses you will find all addresses of our Sales & service partners and Locations.